

# Newport FD - Station 1

City of Newport

Linc\_fir07A

Building Type	County
Fire - City	Lincoln
Street	
245 NW 10th St	
City	State Zip
Newport	OR 97365
Latitude	Longitude
44.64352	124.0552
Tracking Code	Inspection Date
RVS in 2006	8/12/2006



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	-0.5	0	0	0	0	0	2.3
Secondary	PC1	2.6	0	-0.5	0	0	0	0	0	2.1
Tertiary	W2	3.8	0	-0.5	0	2.4	0	0	0	5.7

Newport FD - Station 1

### Final RVS Score

Final Type	Final Score
PC1	2.1

### FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Newport FD - Station 1

Linc\_fir07A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Primary Structural Type	S	Plan Irregularity Primary step in elevation also
		E Secondary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries