

Newport Police Dept

City of Newport

Linc_pol04A

| | | |
|--------------------------------|------------------------------|--------------|
| Building Type Police - City | County Lincoln | |
| Street 169 SW Coast Hwy | | |
| City Newport | State OR | Zip 97365 |
| Latitude 44.63436 | Longitude 124.05335 | |
| Tracking Code RVS in 2006 | Inspection Date 8/16/2006 | |



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 3.8 | -2 | -0.5 | -1 | 0 | 0 | 0 | 0 | 0.3 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |


Newport Police Dept

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2 | 0.3 |

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Newport Police Dept

Linc_pol04A

| | | | |
|--|-----------------------------|---|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | | 1930 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | 1 | Yes | No |
| Plan Irregularities | | Vertical Irregularities | |
| Reentrant Corners: Other | | Steps in Elevation View: 2 to 3 Changes | |
| None | | None | |
| None | | None | |
| Falling Hazards | | Poor Conditions | |
| None | | None | |
| None | | None | |
| None | | None | |
|  | |  | |
| SW Plan Irregularity Primary | | E Plan Irregularity Primary | |
|  | | NE Vertical Irregularity Primary | |