

# Sam Case Elementary School

Lincoln County SD

Linc\_sch02A

Building Type	County
School	Lincoln
Street	
459 NE 12th St	
City	State Zip
Newport	OR 97365
Latitude	Longitude
44.64588	124.04709
Tracking Code	Inspection Date
RVS in 2006	8/12/2006



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sam Case Elementary School

Final RVS Score

Final Type

Final Score

C2

1.3

FEMA-154 Collapse Potential


Moderate (>1%)



OregonGeology

# Sam Case Elementary School

Linc\_sch02A

Enrollment 358	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1950
Total Area (square ft) 44314	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
			
W Plan Irregularity Primary step in elevation also		N Primary Structural Type	
		N General Site covered play area	
		N General Site new addition	
		S General Site new addition	
		S General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries