

Taft Elementary School

Lincoln County SD

Linc_sch03A

Building Type School	County Lincoln	
Street 1545 SE 50th St		
City Lincoln City	State OR	Zip 97367
Latitude 44.92905	Longitude 124.01234	
Tracking Code RVS in 2006	Inspection Date 8/10/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	-1	0	0	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Taft Elementary School

Final RVS Score

Final Type	Final Score
W2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Taft Elementary School

Linc_sch03A

Enrollment 430	Year Built (Field Verified) 1978	Year Built (Alt. Source) 1978	Est. Decade Built 1930
Total Area (square ft) 72363	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
			
S Plan Irregularity Primary		E Vertical Irregularity Primary step in elevation at entryway out-of-plane LFR system also	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Taft Elementary School

Lincoln County SD

Linc_sch03B

Building Type School	County Lincoln	
Street 1545 SE 50th St		
City Lincoln City	State OR	Zip 97367
Latitude 44.92987	Longitude 124.01241	
Tracking Code RVS in 2006	Inspection Date 8/10/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Tertiary		0	0	0	0	0	0	0	0	0

Taft Elementary School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Taft Elementary School

Linc_sch03B

Enrollment 430	Year Built (Field Verified) 1978	Year Built (Alt. Source) 1970	Est. Decade Built 1970
Total Area (square ft) 72363	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
			
NW Vertical Irregularity Primary reentrant corner also		NW Vertical Irregularity Primary primary and secondary structural types also (W2 and S3)	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Taft Elementary School

Lincoln County SD

Linc_sch03C

Building Type School	County Lincoln	
Street 1545 SE 50th St		
City Lincoln City	State OR	Zip 97367
Latitude 44.92926	Longitude 124.01289	
Tracking Code RVS in 2006	Inspection Date 8/10/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	0	0	2.4	0	0	0	6.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Taft Elementary School

Final RVS Score

Final Type	Final Score
W1	6.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Taft Elementary School

Linc_sch03C

Enrollment 430	Year Built (Field Verified) 1978	Year Built (Alt. Source) 1978	Est. Decade Built 1980
Total Area (square ft) 72363	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 SW Primary Structural Type			