

Albany Fire Department

City of Albany

Linn_fir05A

Building Type	County	
Fire - City	Linn	
Street		
110 6th Ave SW		
City	State	Zip
Albany	OR	97321
Latitude	Longitude	
44.63525	123.10664	
Tracking Code	Inspection Date	
Structural Engineering Report		9/15/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Albany Fire Department

Final RVS Score

Final Type	Final Score
C2	2.2

FEMA-154 Collapse Potential

Low (<1%)

No
Planview
Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Albany Fire Department

Linn_fir05A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1948	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
13000	2	No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	