

# Lebanon Fire District Station 31

Lebanon Fire District

Linn\_fir09A

Building Type Fire - RFPD	County Linn	
Street 1050 W Oak St		
City Lebanon	State OR	Zip 97355
Latitude 44.53597	Longitude 122.92289	
Tracking Code RVS in 2006	Inspection Date 7/7/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Tertiary	W2	4.8	-3	-0.5	0	0	0	-1.2	0	0.1

Lebanon Fire District Station 31

## Final RVS Score

Final Type	Final Score
RM1	-0.1

## FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Lebanon Fire District Station 31

Linn\_fir09A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N	General Site	E	Primary Structural Type reentrant corner
			
S	Primary Structural Type		
			
SW	General Site		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries