

Brownsville Rural Fire Dist #61

Linn_fir10A

Brownsville RFPD

Building Type Fire - RFPD	County Linn	
Street 255 N Main St.		
City Brownsville	State OR	Zip 97327
Latitude 44.39312	Longitude 122.98472	
Tracking Code RVS in 2006	Inspection Date 7/7/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Brownsville Rural Fire Dist #61

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Brownsville Rural Fire Dist #61

Linn_fir10A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Internal Discontinuous Diaphram (large internal opening)	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE Plan Irregularity Primary	W General Site	W Other	
		Pounding potential -- building are separate -- and are separate structural types.	
			
NE Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries