

Halsey-Shedd RFPD

Linn_fir18A

Halsey-Shedd RFPD

Building Type		County	
Fire - RFPD		Linn	
Street			
31922 B St			
City	State	Zip	
Shedd	OR	97377	
Latitude		Longitude	
44.45944		123.10911	
Tracking Code		Inspection Date	
RVS in 2006		6/30/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	0	-0.6	0	2.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Halsey-Shedd RFPD

Final RVS Score

Final Type

Final Score

S3

2.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
<input type="text"/>	<input type="text"/>	1993	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
<input type="text"/>	2	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE General Site