

# Sweet Home Fire And Ambulance

Linn\_fir25A

City of Sweet Home

|                |                 |       |
|----------------|-----------------|-------|
| Building Type  | County          |       |
| Fire - City    | Linn            |       |
| Street         |                 |       |
| 25995 1st Ave  |                 |       |
| City           | State           | Zip   |
| Crawfordsville | OR              | 97336 |
| Latitude       | Longitude       |       |
| 44.35487       | 122.85507       |       |
| Tracking Code  | Inspection Date |       |
| RVS in 2006    | 7/7/2006        |       |



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | W1   | 5.2         | 0          | -0.5       | 0        | 1.6        | -0.2   | 0      | 0      | 6.1       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Sweet Home Fire And Ambulance

## Final RVS Score

Final Type

Final Score

W1

6.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Sweet Home Fire And Ambulance

Linn\_fir25A

|                        |                             |                          |                    |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment             | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built  |
|                        |                             | 1991                     | 1980               |
| Total Area (square ft) | Number of Stories           | Basement                 | Pounding Potential |
|                        | 1                           | No                       | No                 |

|                              |                         |
|------------------------------|-------------------------|
| Plan Irregularities          | Vertical Irregularities |
| Torsion: Eccentric Stiffness | None                    |
| None                         | None                    |
| None                         | None                    |

|                 |                 |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| None            | None            |
| None            | None            |
| None            | None            |



NE General Site



SE General Site

