

Sweet Home Fire And Ambulance Cascadia Substation

Linn_fir26A

City of Sweet Home

Building Type	County	
Fire - City	Linn	
Street		
49258 Santiam Hwy		
City	State	Zip
Cascadia	OR	97329
Latitude	Longitude	
44.39829	122.44335	
Tracking Code	Inspection Date	
RVS in 2006	7/3/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	-0.5	0	1.6	-0.2	0	0	6.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sweet Home Fire And Ambulance Cascadia Substation

Final RVS Score

Final Type	Final Score
W1	6.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sweet Home Fire And Ambulance Cascadia Substation

Linn_fir26A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE General Site back of building			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries