

Lebanon Police Dept

City of Lebanon

Linn_pol05A

Building Type		County	
EOC-Public Safety Answering P		Linn	
Street			
40 E Maple St.			
City	State	Zip	
Lebanon	OR	97355	
Latitude		Longitude	
44.53717		122.90644	
Tracking Code		Inspection Date	
RVS in 2006		7/7/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	0	0	0	0	-1.2	0	0.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lebanon Police Dept

Final RVS Score

Final Type

Final Score

W2

0.6

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No

Plan Irregularities	Vertical Irregularities
None	Steps in Elevation View: 2 to 3 Changes
None	None
None	None

Falling Hazards	Poor Conditions
Other: Smokestack	None
None	None
None	None



S Vertical Irregularity Primary



NE General Site

