

# Liberty Elementary School

Greater Albany SD 8J

Linn\_sch06A

Building Type	County
School	Linn
Street	
2345 Liberty St SW	
City	State Zip
Albany	OR 97321
Latitude	Longitude
44.619	123.11819
Tracking Code	Inspection Date
Hasenberg 02	9/15/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	2.4	0	-0.8	0	5.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Liberty Elementary School

### Final RVS Score

Final Type	Final Score
W2	5.4

### FEMA-154 Collapse Potential

Low (<1%)

No  
Planview  
Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Liberty Elementary School

Linn\_sch06A

Enrollment 411	Year Built (Field Verified) 1985	Year Built (Alt. Source) 1985	Est. Decade Built
Total Area (square ft) 37150	Number of Stories 1	Basement	Pounding Potential No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site