

Sunrise Elementary School

Greater Albany SD 8J

Linn_sch09A

Building Type		County	
School		Linn	
Street			
730 19th Ave SE			
City	State	Zip	
Albany	OR	97322	
Latitude		Longitude	
44.62258		123.09388	
Tracking Code		Inspection Date	
Hasenberg 02		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	0	-0.8	0	3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sunrise Elementary School

Final RVS Score

Final Type

Final Score

W2

3

FEMA-154 Collapse Potential

Low (<1%)

No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries


Sunrise Elementary School

Linn_sch09A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
407		1949	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
50648	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site



S General Site