

South Shore Elementary School

Greater Albany SD 8J

Linn_sch10A

Building Type		County	
School		Linn	
Street			
910 Bain St SE			
City	State	Zip	
Albany	OR	97322	
Latitude		Longitude	
44.6338		123.0699	
Tracking Code		Inspection Date	
Hasenberg 02		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	0	-0.8	0	3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

South Shore Elementary School

Final RVS Score

Final Type

Final Score

W2

3

FEMA-154 Collapse Potential

Low (<1%)

No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
410		1971	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
47040	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site