

Hawthorne Elementary School

Sweet Home SD 55

Linn_sch16A

Building Type School	County Linn	
Street 3205 Long St		
City Sweet Home	State OR	Zip 97386
Latitude 44.3984	Longitude 122.70623	
Tracking Code RVS in 2006	Inspection Date 7/3/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	-0.2	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hawthorne Elementary School

Final RVS Score

Final Type	Final Score
W2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



Oregon Geology

Hawthorne Elementary School

Linn_sch16A

Enrollment 343	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built 1940
Total Area (square ft) 24293	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: U shaped None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions None None None	
			
SW Plan Irregularity Primary	SE Plan Irregularity Primary	NW Vertical Irregularity Primary	
			
N Falling Hazard	N Other	N General Site	

Hawthorne Elementary School

Sweet Home SD 55

Linn_sch16B

Building Type School	County Linn	
Street 3205 Long St		
City Sweet Home	State OR	Zip 97386
Latitude 44.39793	Longitude 122.70691	
Tracking Code RVS in 2006	Inspection Date 7/3/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	1.6	0	-1.2	0	5.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hawthorne Elementary School

Final RVS Score

Final Type	Final Score
W2	5.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Hawthorne Elementary School

Linn_sch16B

Enrollment 343	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built 1990
Total Area (square ft) 24293	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
S General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hawthorne Elementary School

Sweet Home SD 55

Linn_sch16C

Building Type School	County Linn	
Street 3205 Long St		
City Sweet Home	State OR	Zip 97386
Latitude 44.3979	Longitude 122.70729	
Tracking Code RVS in 2006	Inspection Date 7/3/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	0	0	1.6	0	-0.6	0	6.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hawthorne Elementary School

Final RVS Score

Final Type	Final Score
W1	6.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hawthorne Elementary School

Linn_sch16C

Enrollment 343	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built 1980
Total Area (square ft) 24293	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 S General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries