

Seven Oak Middle School

Linn_sch21A

Lebanon Community SD 9

Building Type		County	
School		Linn	
Street			
550 Cascade Drive			
City	State	Zip	
Lebanon	OR	97355	
Latitude		Longitude	
44.51058		122.89307	
Tracking Code		Inspection Date	
RVS in 2006		7/7/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	0	-1.2	0	3.1
Secondary	C2	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Tertiary		0	0	0	0	0	0	0	0	0

Seven Oak Middle School

Final RVS Score

Final Type

Final Score

C2

1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
549		1955	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
49572	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NW Plan Irregularity Primary



E General Site



W General Site

