

# Mill City Middle School

Santiam Canyon SD 129J

Linn\_sch25A

Building Type School	County Linn	
Street 450 SW Evergreen St		
City Mill City	State OR	Zip 97360
Latitude 44.75076	Longitude 122.48119	
Tracking Code RVS in 2006	Inspection Date 6/28/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	1.6	0	-1.2	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Mill City Middle School

## Final RVS Score

Final Type	Final Score
W2	1.7

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Mill City Middle School

Linn\_sch25A

Enrollment 212	Year Built (Field Verified) 1987	Year Built (Alt. Source) 1987	Est. Decade Built 1980
Total Area (square ft) 46547	Number of Stories 2	Basement	Pounding Potential No
<b>Plan Irregularities</b> Reentrant Corners: Other None None		<b>Vertical Irregularities</b> Steps in Elevation View: Very Irregular Changes Internal Discontinuous Diaphragm (large internal opening) None	
<b>Falling Hazards</b> None None None		<b>Poor Conditions</b> None None None	
			
E Primary Structural Type		S Vertical Irregularity Primary	
		N Plan Irregularity Primary	