

# Sand Ridge Charter School

Lebanon Community SD 9

Linn\_sch31A

Building Type	County	
School	Linn	
Street		
30581 Sodaville Rd		
City	State	Zip
Lebanon	OR	97355
Latitude	Longitude	
44.48023	122.86994	
Tracking Code	Inspection Date	
RVS in 2006	7/7/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	0	0	0	4.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sand Ridge Charter School

## Final RVS Score

Final Type	Final Score
W2	4.3

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Sand Ridge Charter School

Linn\_sch31A

Enrollment 252	Year Built (Field Verified) 1932	Year Built (Alt. Source) 1932	Est. Decade Built 1970
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None None		Vertical Irregularities Building On Hill or Sloped Site None None	
Falling Hazards None None None		Poor Conditions None None None	
			
SW General Site	E Plan Irregularity Primary	E Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Sand Ridge Charter School

Lebanon Community SD 9

Linn\_sch31B

Building Type School	County Linn	
Street 30581 Sodaville Rd		
City Lebanon	State OR	Zip 97355
Latitude 44.48053	Longitude 122.86952	
Tracking Code RVS in 2006	Inspection Date 7/7/2006	



Seismicity Zone: Moderate

**FEMA 154 Rapid Visual Screening Score Card**

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	0	0	0	0	0	0	3.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

**Sand Ridge Charter School**

**Final RVS Score**

Final Type	Final Score
S3	3.8

**FEMA-154 Collapse Potential**

Low (<1%)
-----------



**OregonGeology**

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Sand Ridge Charter School

Linn\_sch31B

Enrollment 252	Year Built (Field Verified) 1932	Year Built (Alt. Source) 1932	Est. Decade Built 1970
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
S General Site	E Primary Structural Type	NE General Site	

# Sand Ridge Charter School

Lebanon Community SD 9

Linn\_sch31C

Building Type	County	
School	Linn	
Street		
30581 Sodaville Rd		
City	State	Zip
Lebanon	OR	97355
Latitude	Longitude	
44.48014	122.86906	
Tracking Code	Inspection Date	
RVS in 2006	7/7/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	0	0	0	0	0	0	3.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sand Ridge Charter School

## Final RVS Score

Final Type	Final Score
S3	3.8

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Sand Ridge Charter School

Linn\_sch31C

Enrollment 252	Year Built (Field Verified) 1932	Year Built (Alt. Source) 1932	Est. Decade Built 1980
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
SW Primary Structural Type			