

Riverview School

Lebanon Community SD 9

Linn_sch32A

Building Type		County	
School		Linn	
Street			
1011 Mountain River Dr			
City	State	Zip	
Lebanon	OR	97355	
Latitude	Longitude		
44.52626	122.89067		
Tracking Code	Inspection Date		
New Building	9/15/2006		



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Riverview School

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)

**No
Planview
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
471		2002	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions