

Pioneer School

Lebanon Community SD 9

Linn_sch33A

| | |
|---------------|-----------------|
| Building Type | County |
| School | Linn |
| Street | |
| 500 N 5th St | |
| City | State Zip |
| Lebanon | OR 97355 |
| Latitude | Longitude |
| 44.55032 | 122.91419 |
| Tracking Code | Inspection Date |
| New Building | 9/15/2006 |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Pioneer School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| | |

FEMA-154 Collapse Potential

Low (<1%)

No
Planview
Available



Oregon Geology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pioneer School

Linn_sch33A

| | | | |
|------------------------|-------------------------------------|----------------------------------|--------------------|
| Enrollment 471 | Year Built (Field Verified) 2001 | Year Built (Alt. Source) 2001 | Est. Decade Built |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | | No | No |
| Plan Irregularities | | Vertical Irregularities | |
| | | | |
| | | | |
| | | | |
| Falling Hazards | | Poor Conditions | |
| | | | |
| | | | |
| | | | |