

Green Acres School

Lebanon Community SD 9

Linn_sch35A

Building Type	County	
School	Linn	
Street		
700 S 10th St.		
City	State	Zip
Lebanon	OR	97355
Latitude	Longitude	
44.53836	122.92127	
Tracking Code	Inspection Date	
RVS in 2006	7/7/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	-1.2	0	0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Green Acres School

Final RVS Score

Final Type	Final Score
W2	0.1

FEMA-154 Collapse Potential

High (>10%)



Green Acres School

Linn_sch35A

Enrollment 405	Year Built (Field Verified) 1948	Year Built (Alt. Source) 1948	Est. Decade Built 1950
Total Area (square ft) 39334	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: U shaped None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
			
E Falling Hazard	W General Site	W Plan Irregularity Primary	
			
NW Vertical Irregularity Primary	W Falling Hazard	SE General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries