

# Central Elementary School

Greater Albany SD 8J

Linn\_sch37A

Building Type	County	
School	Linn	
Street		
336 9th Ave SW		
City	State	Zip
Albany	OR	97321
Latitude	Longitude	
44.6304	123.10668	
Tracking Code	Inspection Date	
Hasenberg 02	9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	0	0	-0.2	0	0	-0.6	0	1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Central Elementary School

### Final RVS Score

Final Type	Final Score
URM	1

### FEMA-154 Collapse Potential

High (>10%)

No  
Planview  
Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Central Elementary School

Linn\_sch37A

Enrollment 234	Year Built (Field Verified) 1920	Year Built (Alt. Source) 1920	Est. Decade Built
Total Area (square ft) 48453	Number of Stories 3	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S General Site			