

Building Type		County	
Community_College		Malheur	
Street			
650 College Blvd			
City	State	Zip	
Ontario	OR	97914	
Latitude		Longitude	
44.02077		116.97435	
Tracking Code		Inspection Date	
Miller 2004-05		8/11/2005	

Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC2	3.2	-1.5	-0.5	0	0	0	-1.2	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Weese Building

## Final RVS Score

Final Type


Final Score

PC2

0

## FEMA-154 Collapse Potential

Very High (100%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1966	1966	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
23788	2	No	No

Plan Irregularities	Vertical Irregularities
Yes: Unknown	Yes: Unknown

Falling Hazards	Poor Conditions
None	
None	
None	

