

Four Rivers Cultural Center and Museum

Treasure Valley CC

Malh_coc08A

Building Type		County	
Community_College		Malheur	
Street			
676 S.W. 5th Ave			
City	State	Zip	
Ontario	OR	97914	
Latitude		Longitude	
44.02268		116.97284	
Tracking Code		Inspection Date	
New Building		3/1/2007	

Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Four Rivers Cultural Center and Museum


Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1996	1996	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
8472	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions