

Ontario Fire Department

City of Ontario

Malh_fir03A

Building Type		County	
EOC-Public Safety Answering P		Malheur	
Street			
444 SW 4th St			
City	State	Zip	
Ontario	OR	97914	
Latitude		Longitude	
44.02361		116.96875	
Tracking Code		Inspection Date	
RVS in 2006		6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	0	0	-1.6	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ontario Fire Department

Final RVS Score

Final Type


Final Score

RM1

0

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1977	1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
30000	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
Lateral-Force-Resistance in One Direction Only	None
None	None

Falling Hazards	Poor Conditions
Other: Brick Veneer	None
None	None
None	None



W Elevation View



W Elevation View



E Elevation View