

Adrian RFPD

Malh_fir05A

Adrian RFPD

Building Type		County	
Fire - RFPD		Malheur	
Street			
608 First Street			
City	State	Zip	
Adrian	OR	97901	
Latitude		Longitude	
43.73892		117.07209	
Tracking Code		Inspection Date	
RVS in 2006		6/29/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	0	-1.2	0	0.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Adrian RFPD

Final RVS Score

Final Type

Final Score

RM1

0.4

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1964	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
3432	2	No	Yes

Plan Irregularities	Vertical Irregularities
None	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None

