

# Jordan Valley VFD

City of Jordan Valley

Malh\_fir06A

Building Type	County
Fire - City	Malheur
Street	
306 Blackaby St	
City	State Zip
Jordan Valley	OR 97910
Latitude	Longitude
42.97496	117.05534
Tracking Code	Inspection Date
RVS in 2006	6/29/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	0	0	0	0	0	-1.2	4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Jordan Valley VFD

## Final RVS Score

Final Type	Final Score
W1	4

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Jordan Valley VFD

Malh\_fir06A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1900	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
8404	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Elevation View	S	Primary Structural Type



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries