

City of Ontario

Building Type	County
EOC-Public Safety Answering P	Malheur
Street	
444 Southwest 4th St	
City	State Zip
Ontario	OR 97914
Latitude	Longitude
44.02343	116.96883
Tracking Code	Inspection Date
RVS in 2006	6/30/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	0	0	-1.6	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ontario Police Dept

Final RVS Score

Final Type	Final Score
RM1	0

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Ontario Police Dept

Malh_pol02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1977	1977	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
None		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
Other: Brick Veneer		None	
None		None	
			
W	Elevation View	E	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries