

# Cairo Elementary School

Ontario SD 8C

Malh\_sch14A

Building Type	County
School	Malheur
Street	
531 Highway 20/26	
City	State Zip
Ontario	OR 97914
Latitude	Longitude
43.9878	117.01224
Tracking Code	Inspection Date
RVS in 2006	6/30/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	0	0	-1.8	2.5
Secondary	C2	3.6	0	-0.5	0	0	0	0	-1.6	1.5
Tertiary		0	0	0	0	0	0	0	0	0

Cairo Elementary School

## Final RVS Score

Final Type	Final Score
C2	1.5

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Cairo Elementary School

Malh\_sch14A

Enrollment 151	Year Built (Field Verified) 1957	Year Built (Alt. Source) 1957	Est. Decade Built 1950
Total Area (square ft) 16888	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities None None None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
 N Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries