

Branch - Santiam Center (#104)

Mari_coc13A

Chemeketa CC

Building Type		County	
Community_College		Marion	
Street			
11656 Sublimity Rd SE #106			
City	State	Zip	
Santiam	OR	97385	
Latitude	Longitude		
44.83069	122.82085		
Tracking Code	Inspection Date		
Miller 2004-05	6/29/2004		



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Branch - Santiam Center (#104)

Final RVS Score

Final Type

Final Score

RM1

0.3

FEMA-154 Collapse Potential

High (>10%)

No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1992	1992	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
22521	1	No	No

Plan Irregularities	Vertical Irregularities
Yes: Unknown	None

Falling Hazards	Poor Conditions
None	
None	
None	



S General Site

