

Silverton RFPD Victor Point Station #2

Mari_fir03A

Silverton RFPD

Building Type		County	
Fire - RFPD		Marion	
Street			
13404 Riches Rd SE			
City	State	Zip	
Silverton	OR	97381	
Latitude		Longitude	
44.92568		122.78905	
Tracking Code		Inspection Date	
RVS in 2006		8/8/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	-0.5	0	0	0	0	0	3.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Silverton RFPD Victor Point Station #2

Final RVS Score

Final Type

Final Score

W1

3.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Silverton RFPD Victor Point Station #2

Mari_fir03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	None
None	None
None	None


Falling Hazards	Poor Conditions
None	None
None	None
None	None



N Building Name



N Elevation View



E Elevation View



SE Elevation View