

Silverton RFPD Scotts Mills Station

Silverton RFPD

Mari_fir04A

Building Type Fire - RFPD	County Marion	
Street 480 3rd St		
City Scotts Mills	State OR	Zip 97375
Latitude 45.04367	Longitude 122.67109	
Tracking Code RVS in 2006	Inspection Date 8/2/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	0	-0.4	0	0	2.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Silverton RFPD Scotts Mills Station

Final RVS Score

Final Type	Final Score
W2	2.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Silverton RFPD Scotts Mills Station

Mari_fir04A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N	Building Name	S	Elevation View
			
SW	Primary Structural Type	W	Plan Irregularity Primary
			
N	Elevation View	NW	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries