

Sublimity RFPD

Sublimity RFPD

Mari_fir35A

Building Type Fire - RFPD	County Marion	
Street 115 Nw Parker St		
City Sublimity	State OR	Zip 97385
Latitude 44.83103	Longitude 122.79688	
Tracking Code RVS in 2006	Inspection Date 7/19/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	-0.5	0	0	-0.6	0	0	2.7
Secondary	W1	5.2	-3.5	-0.5	0	1.6	-0.2	0	0	2.6
Tertiary		0	0	0	0	0	0	0	0	0

Sublimity RFPD

Final RVS Score


Final Type	Final Score
W1	2.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1949	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
10460	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	General Site	N	General Site
			
NE	General Site		
			
N	General Site	NW	General Site
			
NW	Primary Structural Type		
			
NE	Primary Structural Type	SW	General Site

