

St Paul RFPD

Mari_fir43A

St Paul RFPD

Building Type		County	
Fire - RFPD		Marion	
Street			
4233 Ne Church Ave			
City	State	Zip	
St Paul	OR	97137	
Latitude		Longitude	
45.21082		122.97506	
Tracking Code		Inspection Date	
RVS in 2006		7/27/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	0	0	0	0	-0.6	0	2
Secondary	C2	2.8	-1	0	0	0	0	-0.6	0	1.2
Tertiary		0	0	0	0	0	0	0	0	0

St Paul RFPD

Final RVS Score

Final Type

Final Score

C2

1.2

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1984	1984	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L shaped (Adjacent Build/Entity)	Steps in Elevation View: Single Change
Torsion: Eccentric Stiffness	None
None	None


Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW General Site



S General Site



E Primary Structural Type



E General Site



W Vertical Irregularity Primary



W Falling Hazard



SW Building Name