

Salem Hospital

Pacific Health Horizons NFP

Mari_hos04A

Building Type	County	
Hospital	Marion	
Street		
665 Winter St SE		
City	State	Zip
Salem	OR	97301
Latitude	Longitude	
44.93314	123.03532	
Tracking Code	Inspection Date	
New Building	8/3/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.2	-1	-0.5	0	0	-0.4	0	0	1.3
Secondary	PC1	2.6	0	-0.5	0	0	-0.4	0	0	1.7
Tertiary		0	0	0	0	0	0	0	0	0

Salem Hospital

Final RVS Score

Final Type	Final Score
C2	1.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Salem Hospital

Mari_hos04A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1976	2008	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
800000	6	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
None		Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent)	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
Heavy Cladding (thick stone or concrete)		None	
Other: Heavy cornice or other overhead decoration		None	
			
E	Falling Hazard	NE	Vertical Irregularity Primary
			
N	Primary Structural Type CLADDING JTS		
			
N	Falling Hazard	NW	Elevation View
			
SW	Vertical Irregularity Primary		
			
SW	Primary Structural Type FORM MARKS	S	Elevation View
			
S	Vertical Irregularity Primary		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Salem Hospital

Mari_hos04A



SE General Site
FDN W STREAM



S Primary Structural Type



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Salem Hospital

Pacific Health Horizons NFP

Mari_hos04B

Building Type	County
Hospital	Marion
Street	
665 Winter St SE	
City	State Zip
Salem	OR 97301
Latitude	Longitude
44.93335	123.03574
Tracking Code	Inspection Date
New Building	8/3/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	C1	2.5	-1.5	-0.5	0	0	-0.4	0	0	0.1
Tertiary		0	0	0	0	0	0	0	0	0

Salem Hospital

Final RVS Score

Final Type	Final Score
C1	0.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Salem Hospital

Mari_hos04B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1953	2008	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
800000	3	Yes	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		Short Columns	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW Primary Structural Type	NW Falling Hazard 1990 ADDN	W Vertical Irregularity Tertiary	
			
W Pounding Potential	W Vertical Irregularity Secondary		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries