

Aumsville Police Dept

City of Aumsville

Mari_pol14A

Building Type	County	
Fire - City	Marion	
Street		
125 6th St		
City	State	Zip
Aumsville	OR	97325
Latitude	Longitude	
44.8411	122.87076	
Tracking Code	Inspection Date	
RVS in 2006	7/25/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	0	0	0	0	0	0	4.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Aumsville Police Dept

Final RVS Score

Final Type	Final Score
W1	4.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Aumsville Police Dept

Mari_pol14A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1916	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
2048	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
None		None	
None		None	



W Building Name



SW General Site



E General Site



N Falling Hazard



N Primary Structural Type
wood siding.



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries