

Woodburn Police Dept

City of Woodburn

Mari_pol16A

Building Type Police-City	County Marion	
Street 270 Montgomery St		
City Woodburn	State OR	Zip 97071
Latitude 45.14197	Longitude 122.85941	
Tracking Code RVS in 2006	Inspection Date 8/8/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	W2	3.8	-2	-0.5	0	2.4	0	-0.8	0	2.9
Tertiary		0	0	0	0	0	0	0	0	0

Woodburn Police Dept

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Woodburn Police Dept

Mari_pol16A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1976	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
12885	1	Yes	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Brick Veneer		None	
None		None	
None		None	
			
NE	General Site	S	General Site
		S Elevation View	
			
SW	Basement	NE	Plan Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries