

Oregon State Police

Oregon State Police

Mari_pol25A

Building Type Police - State	County Marion	
Street 255 Capitol St NE # 400		
City Salem	State OR	Zip 97310
Latitude 44.93918	Longitude 123.02867	
Tracking Code RVS in 2006	Inspection Date 7/27/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	2.5	-1.5	-0.5	0	0	-0.4	0	0	0.1
Secondary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Oregon State Police

Final RVS Score

Final Type	Final Score
C1	0.1

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1949	1949	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
29264	1	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Heavy Cladding (thick stone or concrete)		None	
None		None	
None		None	



NE Vertical Irregularity Primary



NW Elevation View



W Elevation View



W Elevation View



W Elevation View



W Field Verified Year Built



SW Elevation View



S Elevation View

