

# Keizer Police Department

City of Keizer

Mari\_pol29A

Building Type		County	
Police - City		Marion	
Street			
930 Chemawa Rd			
City	State	Zip	
Keizer	OR	97303	
Latitude		Longitude	
44.99551		123.02037	
Tracking Code		Inspection Date	
SER & RVS2006		7/20/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	2.4	0	0	-0.8	5.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Keizer Police Department

## Final RVS Score

Final Type

Final Score

W2

5.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Keizer Police Department

Mari\_pol29A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1982	1982	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
10704	1	No	No

  

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

  

Falling Hazards	Poor Conditions
None	None
None	None
None	None



N Building Name



SW Field Verified Year Built



NW General Site



NW General Site



NE General Site



N General Site  
slight change in roof line



SE General Site



E General Site