

# Jefferson High School

Jefferson SD 14J

Mari\_sch07A

Building Type School	County Marion	
Street 336 Talbot Rd		
City Jefferson	State OR	Zip 97352
Latitude 44.73102	Longitude 123.01693	
Tracking Code RVS in 2006	Inspection Date 8/3/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Jefferson High School

### Final RVS Score

Final Type	Final Score
RM1	0.7

### FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Jefferson High School

Mari\_sch07A

Enrollment 288	Year Built (Field Verified) 1980	Year Built (Alt. Source) 1980	Est. Decade Built 1980
Total Area (square ft) 71400	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: T shaped (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
None		None	
None		None	



N Elevation View



W Field Verified Year Built  
1980



SW Elevation View




W Elevation View



S Elevation View



SE Falling Hazard



S Primary Structural Type



NW Other



S General Site



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries



E General Site



# Jefferson High School

Jefferson SD 14J

Mari\_sch07B

Building Type School	County Marion	
Street 336 Talbot Rd		
City Jefferson	State OR	Zip 97352
Latitude 44.73119	Longitude 123.01604	
Tracking Code RVS in 2006	Inspection Date 8/3/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	-0.5	0	0	0	-0.6	0	1.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Jefferson High School

## Final RVS Score

Final Type	Final Score
PC1	1.5

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Jefferson High School

Mari\_sch07B

Enrollment 288	Year Built (Field Verified) 1980	Year Built (Alt. Source) 1980	Est. Decade Built 1980
Total Area (square ft) 71400	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:T shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions Open cracks in structural members None None	
 S Elevation View		 E Poor Condition Tilt up panel has lots of cracks running most of the length of the panel Photos is of cracks on end	 SW Poor Condition Cracks on side
 NE Elevation View		 NW Other	 NW Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries