

# Cummings Elementary School

Salem-Keizer SD 24J

Mari\_sch16A

Building Type	County	
School	Marion	
Street		
613 Cummings Ln N		
City	State	Zip
Keizer	OR	97303
Latitude	Longitude	
44.99037	123.03425	
Tracking Code	Inspection Date	
Structural Engineering Report		
9/15/2006		



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	0	-0.8	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Cummings Elementary School

### Final RVS Score

Final Type	Final Score
C2	0.5

### FEMA-154 Collapse Potential

High (>10%)

No  
Planview  
Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Cummings Elementary School

Mari\_sch16A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
449		1953	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
41287	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions



S General Site



S General Site



S General Site



S General Site