

# Schirle Elementary School

Salem-Keizer SD 24J

Mari\_sch34A

Building Type	County
School	Marion
Street	
4875 Justice Way S	
City	State Zip
Salem	OR 97302
Latitude	Longitude
44.88589	123.07357
Tracking Code	Inspection Date
Structural Engineering Report	9/15/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Schirle Elementary School

### Final RVS Score

Final Type	Final Score
W2	1.3

### FEMA-154 Collapse Potential

Moderate (>1%)

No  
Planview  
Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Schirle Elementary School

Mari\_sch34A

Enrollment 471	Year Built (Field Verified) 1976	Year Built (Alt. Source) 1976	Est. Decade Built
Total Area (square ft) 50958	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries