

| | | |
|-------------------------------|-----------------|-------|
| Building Type | County | |
| School | Marion | |
| Street | | |
| 525 Rockwood St SE | | |
| City | State | Zip |
| Salem | OR | 97306 |
| Latitude | Longitude | |
| 44.87781 | 123.04771 | |
| Tracking Code | Inspection Date | |
| Structural Engineering Report | | |
| 9/15/2006 | | |



Sumpter Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2 | 3.7 |

FEMA-154 Collapse Potential

Low (<1%)

No
Planview
Available



OregonGeology

Sumpter Elementary School

Mari_sch35A

| | | | |
|---------------------------------|-------------------------------------|----------------------------------|--------------------------|
| Enrollment 551 | Year Built (Field Verified) 1979 | Year Built (Alt. Source) 1979 | Est. Decade Built |
| Total Area (square ft) 48352 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities | | Vertical Irregularities | |
| | | | |
| | | | |
| | | | |
| Falling Hazards | | Poor Conditions | |
| | | | |
| | | | |
| | | | |