

# Crossler Middle School

Salem-Keizer SD 24J

Mari\_sch66A

|                 |                 |       |
|-----------------|-----------------|-------|
| Building Type   | County          |       |
| School          | Marion          |       |
| Street          |                 |       |
| 1155 Davis Rd S |                 |       |
| City            | State           | Zip   |
| Salem           | OR              | 97306 |
| Latitude        | Longitude       |       |
| 44.8745         | 123.06341       |       |
| Tracking Code   | Inspection Date |       |
| New Building    | 9/15/2006       |       |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Crossler Middle School

## Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)

# No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

|                        |                             |                          |                    |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment             | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built  |
| 752                    |                             | 1995                     |                    |
| Total Area (square ft) | Number of Stories           | Basement                 | Pounding Potential |
| 107800                 |                             | No                       | No                 |

|                     |                         |
|---------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
|                     |                         |
|                     |                         |
|                     |                         |

|                 |                 |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
|                 |                 |
|                 |                 |
|                 |                 |