

Irrigon Elementary School

Morrow SD 1

Morr_sch03A

| | | |
|----------------|-----------------|-------|
| Building Type | County | |
| School | Morrow | |
| Street | | |
| 490 Se Wyoming | | |
| City | State | Zip |
| Irrigon | OR | 97844 |
| Latitude | Longitude | |
| 45.88584 | 119.49623 | |
| Tracking Code | Inspection Date | |
| New Building | 9/15/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Irrigon Elementary School

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)

No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| 136 | | 2003 | |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | | No | No |

| | |
|---------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
| | |
| | |
| | |

| | |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| | |
| | |
| | |