

GE Building

Mult_coc11A

Mt Hood CC

Building Type		County	
Community_College		Multnomah	
Street			
26000 SE Stark St			
City	State	Zip	
Gresham	OR	97030	
Latitude		Longitude	
45.51202		122.39779	
Tracking Code		Inspection Date	
RVS in 2006		9/14/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	0	0	0	3.8
Secondary	C2	2.8	0	0	0	0	0	0	0	2.8
Tertiary		0	0	0	0	0	0	0	0	0

GE Building

Final RVS Score

Final Type


Final Score

C2

2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

GE Building

Mult_coc11A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	Visable Dry Rot
None	None
None	None



SW Poor Condition



W General Site
Small concrete annex building



S Secondary Structural Type



SW Secondary Structural Type



SW Other
columns



SW General Site
small concrete annex




SW General Site
ge annex (about 3000 sqft)



E Elevation View



SE Elevation View



E Elevation View



SW Other
interior wall



SW Other
exterior wall construction from inside



SW Other
inside north wall



SW General Site
ge annex top

