

Visual Art Center Theatre

Mult_coc14A

Mt Hood CC

Building Type		County	
Community_College		Multnomah	
Street			
26000 SE Stark St			
City	State	Zip	
Gresham	OR	97030	
Latitude		Longitude	
45.51452		122.39499	
Tracking Code		Inspection Date	
RVS in 2006		9/14/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Visual Art Center Theatre

Final RVS Score

Final Type


Final Score

W2

1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Visual Art Center Theatre

Mult_coc14A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Very Irregular Changes
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None




N General Site
BLDG TOO SMALL TO SCREEN



NE Elevation View



E Plan Irregularity Primary



N General Site
BLDG TOO SMALL TO SCREEN



SE Plan Irregularity Primary



SE Plan Irregularity Primary



SW Elevation View



W Elevation View