

Cascade - Jackson Hall

Mult_coc16A

Portland CC

Building Type		County	
Community_College		Multnomah	
Street			
705 N Killingsworth St			
City	State	Zip	
Portland	OR	97217	
Latitude		Longitude	
45.56382		122.67242	
Tracking Code		Inspection Date	
RVS2006 & FEMA154		6/29/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Cascade - Jackson Hall

Final RVS Score

Final Type


Final Score

C2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Cascade - Jackson Hall

Mult_coc16A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1985	1985	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
26302	2	No	No

Plan Irregularities	Vertical Irregularities
Yes: Unknown	Yes: Unknown
None	None
None	None


Falling Hazards	Poor Conditions
Other: Light Cladding	None
None	None
None	None



NW Plan Irregularity Primary



W Elevation View



SW Plan Irregularity Primary



SE Plan Irregularity Primary



SE Elevation View



E Plan Irregularity Primary