

Cascade - Moriarty Arts and Humanities Building

Mult_coc19A

Portland CC

Building Type	County
Community_College	Multnomah
Street	
705 N. Killingsworth St	
City	State Zip
Portland	OR 97217
Latitude	Longitude
45.56299	122.67461
Tracking Code	Inspection Date
Missed	3/1/2007

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Cascade - Moriarty Arts and Humanities Building

Final RVS Score

Final Type Final Score

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Cascade - Moriarty Arts and Humanities Building

Mult_coc19A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	