


Cascade - Gymnasium

Mult_coc23A

Portland CC

Building Type		County	
<input type="text" value="Community_College"/>		<input type="text" value="Multnomah"/>	
Street			
<input type="text" value="705 N. Killingsworth St"/>			
City	State	Zip	
<input type="text" value="Portland"/>	<input type="text" value="OR"/>	<input type="text" value="97217"/>	
Latitude		Longitude	
<input type="text" value="45.56246"/>		<input type="text" value="122.67347"/>	
Tracking Code		Inspection Date	
<input type="text" value="New Building"/>		<input type="text" value="3/1/2007"/>	

Seismicity Zone: High										Cascade - Gymnasium Final RVS Score Final Type Final Score <input type="text"/> <input type="text"/>	
FEMA 154 Rapid Visual Screening Score Card											
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score	
Primary		0	0	0	0	0	0	0	0	0	
Secondary		0	0	0	0	0	0	0	0	0	
Tertiary		0	0	0	0	0	0	0	0	0	
FEMA-154 Collapse Potential										<input type="text" value="Low (<1%)"/>	



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
<input type="text"/>	<input type="text" value="2004"/>	<input type="text" value="2004"/>	<input type="text"/>
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
<input type="text" value="31882"/>	<input type="text" value="2"/>	<input type="text" value="No"/>	<input type="text" value="No"/>

Plan Irregularities	Vertical Irregularities
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

Falling Hazards	Poor Conditions
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>